

# Airworthiness Directive Schedule

## Aeroplanes

### Hawker Beechcraft Corporation 77 Series (Skipper)

28 August 2008

---

- Notes**
1. This AD schedule is applicable to Hawker Beechcraft Corporation 77 aircraft (formally Raytheon Aircraft Company and Beech Aircraft Company), manufactured under Federal Aviation Administration (FAA) Type Certificate No. A30CE.
  2. The date above indicates the amendment date of this schedule.
  3. New or amended ADs are shown with an asterisk \*

### Contents

DCA/B77/1	Shoulder Harness Installation - Inspection .....	2
DCA/B77/2	Wing Structure - Fatigue Life Limitation .....	2
DCA/B77/3	Rudder Balance Weight Installation - Modification .....	2
DCA/B77/4	Electrical System - Modification .....	2
DCA/B77/5	NLG Fork - Inspection .....	2
DCA/B77/6	Cancelled – Purpose Fulfilled.....	3
* DCA/B77/7	Circuit Breaker Toggle Switches – Replacement .....	3

- DCA/B77/1      Shoulder Harness Installation - Inspection**
- Applicability:** Model 77 S/N WA-3 through WA-235, WA-237, WA-238, WA-240 through WA-254, WA-256, WA-258, WA-261 through WA-264, WA-266, WA-267 and WA-269.
- Requirement:** Inspect per Beechcraft SI 1173 Rev.1. Rectify incorrect installations as prescribed before further flight.  
(FAA AD 82-09-03 refers).
- Compliance:** Within next 50 hours TIS.
- Effective Date:** 25 June 1982
- DCA/B77/2      Wing Structure - Fatigue Life Limitation**
- Applicability:** All model 77
- Requirement:** Retire basic wing structure at 12,000 hours TTIS.
- Effective Date:** 24 September 1982
- DCA/B77/3      Rudder Balance Weight Installation - Modification**
- Applicability:** Model 77 S/N WA-1 through WA-312.
- Requirement:** To preclude possibility of rudder control loss, or flutter, modify per Beechcraft SI 1256.  
(FAA AD 83-23-03 refers).
- Compliance:** Within next 25 hours TIS.
- Effective Date:** 16 December 1983
- DCA/B77/4      Electrical System - Modification**
- Applicability:** Model 77, S/N WA-1 through WA-312.
- Requirement:** To prevent diode overheating and smoke in cockpit, modify per Beechcraft SB 2201 Rev.1.
- Compliance:** Within next 100 hours TIS.
- Effective Date:** 13 May 1988
- DCA/B77/5      NLG Fork - Inspection**
- Applicability:** Model 77, S/N WA-1 through WA-312 not fitted with P/N 108-820010-653 fork and axle assembly.
- Requirement:** To prevent failure of the NLG fork accomplish the following:
1. Fluorescent penetrant inspect the fork for cracks per Beechcraft SB 2241 Rev.1.  
If found cracked, replace the fork and axle assembly with a P/N 108-820010-653 fork and axle assembly before further flight.
  2. Visually inspect the NLG fork axle assembly.  
(FAA AD 91-23-01 refers)
- Compliance:** 1. Fluorescent inspection within next 50 hours TIS and thereafter at intervals not to exceed 500 hours TIS.

2. Between fluorescent inspections, visually inspect at intervals not to exceed 100 hours TIS.

**Effective Date:** 20 December 1991

**DCA/B77/6**                    **Cancelled – Purpose Fulfilled**

**\* DCA/B77/7**                    **Circuit Breaker Toggle Switches – Replacement**

**Applicability:** Model 77 aircraft, S/N WA-1 through to WA-312

Fitted with circuit breaker toggle switches P/N 35-380132-1 through to P/N 35-380132-53.

**Requirement:** To prevent failure of affected circuit breaker toggle switches due to possible overheating which could result in smoke in the cockpit and the inability to turn the switch off, accomplish the following:

1. Replace all affected circuit breaker toggle switches with an improved circuit breaker toggle switch P/N 35-380132-61 through to 35-380132-113 as applicable, per the instructions in Hawker Beechcraft SB 24-3807, issued May 2007, and Raytheon Aircraft Company SB 24-3735, issued August 2005.
2. An affected circuit breaker shall not be fitted to any aircraft.

(FAA AD 2008-13-17 refers)

**Compliance:**

1. By 28 August 2009.
2. From 28 August 2008.

**Effective Date:** 28 August 2008