

Airworthiness Directive Schedule
Propellers and Propeller Governors
Woodward Constant Speed Propeller Governors
26 May 2011

The date above indicates the amendment date of this schedule.

New or amended ADs are shown with an asterisk *

Contents

DCA/WOOD/101	Cancelled - Purpose Fulfilled	2
DCA/WOOD/102	Cancelled - Purpose Fulfilled	2
DCA/WOOD/103	Cancelled - Purpose Fulfilled	2
* DCA/WOOD/104	Cancelled – Purpose fulfilled.....	2
* DCA/WOOD/105	Cancelled – Purpose fulfilled.....	2
DCA/WOOD/106	Flyweight Retaining Ring - Modification	2
DCA/WOOD/107	Coil Retaining Screws Safety Wire - Inspection	2
DCA/WOOD/108	Cancelled by DCA/WOOD/109	2
* DCA/WOOD/109	Cancelled – Purpose fulfilled.....	2
* DCA/WOOD/110	Cancelled – Purpose fulfilled.....	2
* DCA/WOOD/111	Cancelled – Purpose fulfilled.....	2
* DCA/WOOD/112	Cancelled – Purpose fulfilled.....	2
* DCA/WOOD/113	Cancelled – Purpose fulfilled.....	3
DCA/WOOD/114	Governor - Removal from Service.....	3
* DCA/WOOD/115	Propeller Governors – Inspection and Rework.....	3

- DCA/WOOD/101** **Cancelled - Purpose Fulfilled**
- DCA/WOOD/102** **Cancelled - Purpose Fulfilled**
- DCA/WOOD/103** **Cancelled - Purpose Fulfilled**
- * **DCA/WOOD/104** **Cancelled – Purpose fulfilled**
Effective Date: 26 May 2011
- * **DCA/WOOD/105** **Cancelled – Purpose fulfilled**
Effective Date: 26 May 2011
- DCA/WOOD/106** **Flyweight Retaining Ring - Modification**
Applicability: As detailed
Requirement: Woodward SB 33522
Compliance: Within the next 100 hours TIS
Effective Date: 30 September 1960
- DCA/WOOD/107** **Coil Retaining Screws Safety Wire - Inspection**
Applicability: As detailed in FAA AD 70-16-1
Background: To prevent uncontrolled feathering
Requirement: All affected governors are to be inspected in accordance with the provisions of FAA AD 70-16-1
Compliance: Within the next 50 hours flight time
Note: Operators notified of this requirement 8 September
Effective Date: 31 October 1970
- DCA/WOOD/108** **Cancelled by DCA/WOOD/109**
- * **DCA/WOOD/109** **Cancelled – Purpose fulfilled**
Effective Date: 26 May 2011
- * **DCA/WOOD/110** **Cancelled – Purpose fulfilled**
Effective Date: 26 May 2011
- * **DCA/WOOD/111** **Cancelled – Purpose fulfilled**
Effective Date: 26 May 2011
- * **DCA/WOOD/112** **Cancelled – Purpose fulfilled**
Effective Date: 26 May 2011

*** DCA/WOOD/113 Cancelled – Purpose fulfilled****Effective Date:** 26 May 2011**DCA/WOOD/114 Governor - Removal from Service****Applicability:** Model F210681 governors S/N 1446751 through 1446783, 1446785 through 1446806, 1446808, 1446809, 1446811, 1446812, 1446814 through 1446817, 1567547 through 1567562, 1567564 through 1567594 and 1567596 through 1567612 installed on Maule M-5-235C aircraft**Requirement:** To prevent possible flyweight failure remove affected governors from service and replace with governor having S/N not included in applicability listing. Woodward SB 33576 refers (FAA AD 81-25-01 also refers)**Compliance:** Within the next 50 hours TIS**Effective Date:** 29 January 1982*** DCA/WOOD/115 Propeller Governors – Inspection and Rework****Applicability:** Woodward governor models 210452, A210452, B210452, C210452, D210452, E210452, F210452, G210452, H210452, J210452, K210452, L210452, M210452, P210452, 210453, 210458, 210460, B210460, 210462, A210462, 210472, and C210472 with S/N below 992601 which were manufactured prior to 1970 and used on single reciprocating engine aircraft.

These Woodward governor models may be installed on but not limited to the following single engine aircraft: BEECH models E33, F33, E33A, E33C, F33A, F33C, 35-33, 35-A33, 35-B33, 35-C33, 35-C33A, H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B, 36 and A36 aircraft, BELLANCA models 14-19-3A, 17-30, 17-30A, 17-31, 17-31A, 17-31TC, 17-31ATC aircraft, CESSNA models 180, 180A, 180B, 180C, 180D, 180E, 180F, 180G, 180H, 182, 182A, 182B, 182C, 182D, 182E, 182F, 182G, 182H, 182J, 182K, 182L, 182M, 182N, 185, 185A, 185B, 185C, 185D, 185E, A185E, 188, A188, 188A, A188A, 206, U206, P206, U206A, P206A, P206B, TU206A, TU206B, TP206A, TP206B, U206B, P206C, TP206C, P206D, TP206D, P206E, TP206E, U206C, TU206C, U206D, TU206D, U206E, TU206E, 207, T207, 210B, 210C, 210-5(205), 210-5A(205A), 210D, 210E, T210F, 210F, T210G, T210H, 210G, 210H, T210J, 210J, 210K and T210K aircraft, MAULE models M-4-210, M-4-210C, M-4-210S, M-4-210T, M-4-220, M-4-220C, M-4-220S, M-4-220T and M-4-180 aircraft, MOONEY models M20C and M20D aircraft and NAVION H model aircraft.

Note: The date of manufacture can be determined from a decal attached to the governor body which shows the quarter and the year. Example: "1Q70" indicates first quarter 1970.**Requirement:** To prevent loss of propeller control accomplish the requirements in FAA AD 70-26-02.

(FAA AD 70-26-02 refers)

Compliance: By 26 May 2012, unless previously accomplished.**Effective Date:** 26 May 2011