

Source of Aerodrome QNH

This table only lists aerodromes that have RNAV (GNSS) instrument approach charts and QNH availability stated.

1	2	3
Aerodrome	Indicator	RNAV Chart Annotation
Alexandra	NZLX	Use AD QNH
Ardmore	NZAR	Use AD QNH
Ashburton	NZAS	Use AD QNH
Auckland	NZAA	Use AD QNH
Bay of Islands Hospital	NZJI	Use Remote QNH
Chatham Is	NZCI	Use AD QNH
Christchurch	NZCH	Use AD QNH
Coromandel	NZCX	Use Remote QNH
Dargaville Hospital	NZJE	Use Remote QNH
Dunedin	NZDN	Use AD QNH
Dunedin Hospital	NZDH	Use Remote QNH
Gisborne	NZGS	Use AD QNH
Glentanner	NZGT	Use NZMC QNH only
Great Barrier	NZGB	Use Remote QNH
Great Mercury	NZGR	Use Remote QNH
Greymouth	NZGM	Use Remote QNH
Hamilton	NZHN	Use AD QNH
Hastings	NZHS	Use Remote QNH
Hawera	NZHA	Use Remote QNH
Hokitika	NZHK	Use AD QNH
Invercargill	NZNV	Use AD QNH
Kaitaia	NZKT	Use AD QNH
Kaitaia Hospital	NZJK	Use Kaitaia Hospital QNH
Kerikeri	NZKK	Use AD QNH
Masterton	NZMS	Use AD QNH
Mechanics Bay	NZMB	Use Mechanics Bay QNH
Napier	NZNR	Use AD QNH
Nelson	NZNS	Use AD QNH
New Plymouth	NZNP	Use AD QNH
North Shore	NZNE	Use Remote QNH
Oamaru	NZOU	Use AD QNH
Ohakea	NZOH	Use AD QNH
Palmerston North	NZPM	Use AD QNH
Paraparaumu	NZPP	Use AD QNH
Pauanui Beach	NZUN	Use Remote QNH
Pikes Point	NZPK	Use Remote QNH
Queenstown	NZQN	Use NZQN QNH only
Rotorua	NZRO	Use AD QNH

Southland – Kew Hospital	NZJS	Use Remote QNH
Spring Hill	NZSL	Use Remote QNH
Takaka	NZTK	Use Remote QNH
Taumarunui Hospital	NZJT	Use Remote QNH
Taupo	NZAP	Use AD QNH
Tauranga	NZTG	Use AD QNH
Te Anau/ Manapouri	NZMO	Use AD QNH only
Te Kuiti Hospital	NZTQ	Use Remote QNH
Thames	NZTH	Use Remote QNH
Timaru	NZTU	Use AD QNH
Tokoroa	NZTO	Use Remote QNH
Wairoa	NZWO	Use AD QNH
Wanaka	NZWF	Use AD QNH
Wellington	NZWN	Use AD QNH
Wellsford	NZWJ	Use Remote QNH
Westport	NZWS	Use AD QNH
Whakatane	NZWK	Use AD QNH
Whangamata	NZWG	Use Remote QNH
Whanganui	NZWU	Use AD QNH
Whangarei	NZWR	Use AD QNH
Whenuapai	NZWP	Use AD QNH
Whitianga	NZWT	Use AD QNH
Woodbourne	NZWB	Use AD QNH

Notes:

Columns 1 & 2 – Name of the aerodrome and four-letter location (Icn) indicator as shown on the instrument approach procedure charts (AIP NZ).

Column 3 – Indicates need to apply the remote QNH procedure as there is no QNH source on the aerodrome. Details about the use of remote QNH are provided in *AIP New Zealand, ENR 1.5, Departing, Holding and Approach Procedures*.

Note: At present there are some inconsistencies in the QNH statements on the aerodrome plates in the AIP, but these are being amended through the normal AIRAC cycle to provide alignment with this table.