

**List of NZ CAA ADs issued in the last 27 months as at Amendment Nr 18-06**

AD Schedule*	AD	AD Title	Eff Date
<b>Aeroplanes</b>	<b>Aeroplanes</b>		
Aeroplanes General – Small (Up to 5700 kg MCTOW)	DCA/GEN/32	Cancelled – FAA AD 2004-21-05 refers	28-Sep-17
Aeroplanes General – Small (Up to 5700 kg MCTOW)	FAA AD 2004-21-05	Kelly Aerospace Power Systems B-series Combustion Heaters - Inspection	28-Sep-17
Aircraft - General (Less than 5700kg MCTOW)	DCA/GEN/36A	Parts Manufactured by Croydon Aircraft Company	9-Mar-18
Aircraft - General (Less than 5700kg MCTOW)	FAA AD 2017-06-03	Stewart Warner South Wind Combustion Heaters - Inspection	5-May-17
Aircraft General	DCA/GEN/15	Cancelled - Purpose fulfilled	27-Jul-17
Aircraft General	DCA/GEN/17	Cancelled - Purpose fulfilled	27-Jul-17
Aircraft General	DCA/GEN/18	Cancelled - Purpose fulfilled	27-Jul-17
Aircraft General	DCA/GEN/21	Cancelled - Purpose fulfilled	27-Jul-17
Aircraft General	DCA/GEN/22	Cancelled - Purpose fulfilled	27-Jul-17
Aircraft General	DCA/GEN/24	Cancelled - Purpose fulfilled	27-Jul-17
Alexandria 17-30/31 Series	FAA AD 2005-01-19	Mode S Transponders	28-Apr-16
Alexandria 17-30/31 Series	FAA AD 2006-03-08	Vacuum Pumps	28-Apr-16
Alexandria 17-30/31 Series	FAA AD 2008-05-11	Muffler and Tail Pipe Assemblies	28-Apr-16
Alexandria 17-30/31 Series	FAA AD 2014-20-12	Fuselage	28-Apr-16
Alexandria 17-30/31 Series	FAA AD 72-01-03	Engine Fuel Hose – Inspection	28-Apr-16
Alexandria 17-30/31 Series	FAA AD 73-03-03	Engine Induction Box Bolts – Inspection	28-Apr-16
Alexandria 17-30/31 Series	FAA AD 73-05-02	Rudder Control System – Inspection	28-Apr-16
Alexandria 17-30/31 Series	FAA AD 75-11-06	Check Valve – Inspection	28-Apr-16
Alexandria 17-30/31 Series	FAA AD 76-08-04	Wood Deterioration – Inspection	28-Apr-16
Alexandria 17-30/31 Series	FAA AD 77-22-02	Nose Landing Gear Engine Mount – Inspection	28-Apr-16
Alexandria 17-30/31 Series	FAA AD 86-25-06	Wing Main and Auxiliary Fuel Tanks – Inspection	28-Apr-16
Alexandria 17-30/31 Series	FAA AD 87-11-01R1	Fuel Caps and Drains – Inspection	28-Apr-16
Alexandria 17-30/31 Series	FAA AD 90-02-17	Landing Gear Fitting Assemblies	28-Apr-16
Alexandria 17-30/31 Series	FAA AD 96-18-07	Nose Landing Gear Drag Strut Brackets	28-Apr-16
Alexandria 17-30/31 Series	FAA AD 98-21-21R1	Electric Inflatable Door Seals	28-Apr-16
American Champion 7 and 8 Series	FAA AD 2017-07-10	Aileron Hinge Rib and Support - Inspection	12-Apr-17
Beechcraft 300LW	FAA AD 2002-23-11	Elevator Balance Weight Attachment Screws - Inspection	30-Jun-16
Beechcraft 300LW	FAA AD 2004-17-02	Cross Shaft Attach Bolt - Inspection	30-Jun-16
Beechcraft 300LW	FAA AD 2005-01-19	Mode S Transponders - Inspection	30-Jun-16

Beechcraft 300LW	FAA AD 74-08-09R3	Equipment and Furnishing - Inspection	30-Jun-16
Beechcraft 300LW	FAA AD 89-22-14	Aileron Flutter - Inspection	30-Jun-16
Beechcraft 300LW	FAA AD 91-12-10	Wing Spar Attachment - Inspection	30-Jun-16
Beechcraft 300LW	FAA AD 98-08-20	Autopilot Servo Actuators - Inspection	30-Jun-16
Beechcraft 300LW	FAA AD 98-25-02	Top Mounted Antenna - Inspection	30-Jun-16
Beechcraft 35 & 36 series	FAA AD 2018-06-11	Exhaust Tailpipe V-band Coupling - Inspection	3-May-18
Cessna 175 Series	DCA/CESS175/7	Cancelled – FAA AD 2016-14-05 Refers	11-Aug-16
Cessna 175 Series	FAA AD 2016-14-05	Engine Mounting Brackets – Inspection	11-Aug-16
Cessna 177 Series	FAA AD 71-24-04	Fuel and Oil Flexible Hose Assemblies - Inspection	29-Sep-16
Cessna 182 Series	DCA/CESS182/153A	Cancelled – FAA AD 72-07-09 refers	25-Aug-16
Cessna 182 Series	FAA AD 72-07-09	Vertical Stabiliser - Inspection	25-Aug-16
Cessna 206 Series	DCA/CESS206/112	Cancelled – FAA AD 71-24-04 refers	29-Sep-16
Cessna 206 Series	DCA/CESS206/155B	Cancelled – FAA AD 72-07-09 refers	25-Aug-16
Cessna 206 Series	FAA AD 2002-26-03	Brackett Single Screen Air Filter Assemblies - Inspection	29-Sep-16
Cessna 206 Series	FAA AD 2006-03-08	ADV211CC and ADV212CW Vacuum Pumps - Inspection	29-Sep-16
Cessna 206 Series	FAA AD 71-24-04	Fuel and Oil Flexible Hose Assemblies - Inspection	29-Sep-16
Cessna 206 Series	FAA AD 72-07-09	Vertical Stabiliser - Inspection	25-Aug-16
Cessna 206 Series	FAA AD 86-24-07	Engine Controls - Inspection	29-Sep-16
Cessna 207 Series	DCA/CESS207/31A	Cancelled – FAA AD 72-07-09 refers	25-Aug-16
Cessna 207 Series	FAA AD 72-07-09	Vertical Stabiliser - Inspection	25-Aug-16
Cessna 210 Series	DCA/CESS210/43B	Cancelled – FAA AD 72-07-09 refers	25-Aug-16
Cessna 210 Series	FAA AD 72-07-09	Vertical Stabiliser - Inspection	25-Aug-16
Cessna 310 & 320 Series	FAA AD 2016-07-24	Cancelled – FAA AD 2016-17-08 refers	12-Sep-16
Cessna 310 & 320 Series	FAA AD 2016-17-08	Elevator Trim Push-pull Rod – Inspection	12-Sep-16
Cessna 337 Series	DCA/CESS337/1	Cancelled – FAA AD 71-24-04 refers	29-Sep-16
Cessna 337 Series	FAA AD 71-24-04	Fuel and Oil Flexible Hose Assemblies - Inspection	29-Sep-16
Cessna 402 and 421 Series	FAA AD 2018-03-03R1	Carry Through Spars – Inspection	31-May-18
Cessna 402 Series	FAA AD 2016-07-24	Cancelled – FAA AD 2016-17-08 refers	12-Sep-16
Cessna 402 Series	FAA AD 2016-17-08	Elevator Trim Push-pull Rod – Inspection	12-Sep-16
Cessna 402 Series	FAA AD 2017-10-09	Nacelle Fittings – Inspection	29-Jun-17
Cessna 421 Series	FAA AD 2016-07-24	Cancelled – FAA AD 2016-17-08 refers	12-Sep-16
Cessna 421 Series	FAA AD 2016-17-08	Elevator Trim Push-pull Rod – Inspection	12-Sep-16

Cessna 510 series	FAA AD 2018-07-13	Brake Assembly - Inspection	15-May-18
De Havilland DH60 Series	DCA/DH60/111B	Croydon Manufactured Spars – Inspection	28-Feb-18
De Havilland DH60 Series	UK CAA AD 007-03-99	Cockpit Safety Harness Installation – Inspection and Life Limitation	31-Aug-17
De Havilland DH82 Series	DCA/DH82/129B	Croydon Manufactured Spars – Inspection	28-Feb-18
De Havilland DH82 Series	UK CAA AD 007-03-99	Cockpit Safety Harness Installation – Inspection and Life Limitation	31-Aug-17
De Havilland DH83 Series	DCA/DH83/105B	Croydon Manufactured Spars – Inspection	28-Feb-18
De Havilland DH83 Series	UK CAA AD 007-03-99	Cockpit Safety Harness Installation – Inspection and Life Limitation	31-Aug-17
De Havilland DH94 Series	UK CAA AD 007-03-99	Cockpit Safety Harness Installation – Inspection and Life Limitation	31-Aug-17
De Havilland DHC-1 (Chipmunk)	DCA/DHC-1/107	Cancelled - DCA/DHC-1/152A refers (TC AD CF-49-05)	26-Oct-17
De Havilland DHC-1 (Chipmunk)	DCA/DHC-1/117A	Engine Throttle and Mixture Control Rods - Inspection	22-Feb-18
De Havilland DHC-1 (Chipmunk)	DCA/DHC-1/137B	Spin Recovery Advisory Placard - Modification	22-Feb-18
De Havilland DHC-1 (Chipmunk)	TC AD CF-54-02	Canopy Lock - Modification	26-Oct-17
De Havilland DHC-1 (Chipmunk)	TC AD CF-91-38	Fuselage Rear Bulkhead - Inspection	26-Oct-17
De Havilland DHC-1 (Chipmunk)	UK CAA AD 2794 PRE 80 (revised)	Fuel Filter Mounting - Modification	22-Feb-18
De Havilland DHC-1 (Chipmunk)	UK CAA AD 2795 PRE 80 (revised)	Fuel Feed Pipe - Modification	22-Feb-18
De Havilland DHC-1 (Chipmunk)	UK CAA AD 2796 PRE 80 (revised)	Balanced Type Vents - Modification	22-Feb-18
De Havilland DHC-1 (Chipmunk)	UK CAA AD 2797 PRE 80 (revised)	Flexible Mounted Aerial - Modification	22-Feb-18
De Havilland DHC-1 (Chipmunk)	UK CAA AD 2799 PRE 80 (revised)	Anti-spinning Strakes - Modification	21-Dec-17
De Havilland DHC-1 (Chipmunk)	UK CAA AD 2801 PRE 80 (revised)	Aerobatics and Spins Prohibited Placard - Modification	21-Dec-17
De Havilland DHC-2 (Beaver)	TC AD CF-2017-17	Flap/Aileron Hinge Arm Support Brackets and Rear Spar Web - Inspection	1-Jun-17
De Havilland DHC-2 (Beaver)	TC AD CF-2017-33	Airframe Corrosion - Inspection	26-Oct-17
De Havilland DHC-2 (Beaver)	Transport Canada AD CF-2018-10	Wire Pull Fittings - Inspection	26-Apr-18
De Havilland DHC-3 (Otter)	TC AD CF-2016-05R1	Levelling and Weighing – AFM Amendment	29-Jun-17
De Havilland DHC-3 (Otter)	TC AD CF-2017-11	Wing Strut Attach Bolts – Inspection	23-Mar-17
De Havilland DHC-3 (Otter)	TC AD CF-2017-29	Main Wing Spar Lug Fitting and Tie-bar – Inspection	7-Sep-17
De Havilland DHC-3 (Otter)	TC AD CF-2018-04	Airframe Corrosion and Cracking – Inspection	2-Feb-18
Diamond DA40 Series	EASA AD 2016-0126	Alternator Cable - Inspection	6-Jul-16
Diamond DA40 Series	EASA AD 2017-0086	Electronic Control Unit – Modification	26-May-17
Diamond DA42 Series	EASA AD 2016-0156R1	Cancelled – EASA AD 2017-0090 refers	31-May-17
Diamond DA42 Series	EASA AD 2017-0074	Flap Control System / Bellcrank Assembly – Inspection	12-May-17

Diamond DA42 Series	EASA AD 2017-0090	Cancelled – EASA AD 2017-0120 refers	27-Jul-17
Diamond DA42 Series	EASA AD 2017-0120	Cancelled - EASA AD 2017-0254 refers	25-Jan-18
Diamond DA42 Series	EASA AD 2017-0254	Exhaust Pipes – Inspection	25-Jan-18
Gippsland GA8 series	CASA AD/GA8/7 Amdt 1	Fuel System Ventilation and Drainage - Modification	30-Nov-17
Gippsland GA8 series	CASA AD/GA8/9 Amdt 1	Wing Strut and Wing Strut Fittings - Inspection	8-Jun-18
Helio H-250 (Courier)	FAA AD 82-16-08	Wing Spar - Inspection	27-Oct-16
Jabiru Aeroplanes	CASA AD/JABIRU/2	Wing Attachment Bolts - Life Limit	22-May-17
Lake LA-4, Lake LA-4-200 and Lake Model 250 Aeroplanes	FAA AD 74-09-06	Fuel Restrictor Fitting - Inspection	28-Sep-17
Lake LA-4, Lake LA-4-200 and Lake Model 250 Aeroplanes	FAA AD 76-02-01	Engine Power - Inspection	28-Sep-17
Lake LA-4, Lake LA-4-200 and Lake Model 250 Aeroplanes	FAA AD 76-12-11	Engine Power - Inspection	28-Sep-17
Lake LA-4, Lake LA-4-200 and Lake Model 250 Aeroplanes	FAA AD 76-24-02	Engine Oil Coolers - Inspection	28-Sep-17
Lake LA-4, Lake LA-4-200 and Lake Model 250 Aeroplanes	FAA AD 78-14-05	Main Beam Fittings - Inspection	28-Sep-17
Lake LA-4, Lake LA-4-200 and Lake Model 250 Aeroplanes	FAA AD 79-06-01	Engine Mounts with Cracked Straps - Inspection	28-Sep-17
Lake LA-4, Lake LA-4-200 and Lake Model 250 Aeroplanes	FAA AD 81-15-03	Engine Inlet Air Filters - Inspection	28-Sep-17
McDonnell Douglas DC-3	DCA/DC3/108B	Fuel Selector Valve - Modification	30-Jun-16
Mitsubishi MU-2B Series	DCA/MU2/24A	Icing Awareness – AFM Revision and Pilot Training	28-Jun-18
Mitsubishi MU-2B Series	JCAB AD TCD-8783-2016	Wing Spacer Plates - Inspection	12-Jul-16
Nanchang CJ-6	DCA/CJ6/2B	Pneumatic System Reservoirs – Inspection	23-Feb-17
Pacific Aerospace 750XL	DCA/750XL/18B	Fin Forward Pickup – Inspection	28-Feb-18
Pacific Aerospace 750XL	DCA/750XL/19A	Engine Oil Pressure Indicator - Inspection	26-Apr-18
Pacific Aerospace 750XL	DCA/750XL/20	Fuel Tank Caps - Inspection	15-Dec-17
Pacific Aerospace 750XL	DCA/750XL/21	Wing Lightning Protection Panels - Inspection	22-Dec-17
Pacific Aerospace 750XL	DCA/750XL/22A	Ventilation Hose behind Instrument Panel - Inspection	28-Feb-18
Pacific Aerospace 750XL	DCA/750XL/23	Cockpit Control Handles - Inspection	28-Dec-17
Pacific Aerospace 750XL	DCA/750XL/24A	Pitot Static Tube Support Clamps - Inspection	22-Mar-18
Pacific Aerospace 750XL	DCA/750XL/25A	Wing Leading Edge Tank Abrasion - Inspection	22-Mar-18
Pacific Aerospace 750XL	DCA/750XL/26	Rudder and Elevator Trim Drive Coupling - Modification	28-Feb-18
Pacific Aerospace 750XL	DCA/750XL/27A	Firewall Sound Insulation - Inspection	1-Mar-18
Pacific Aerospace 750XL	DCA/750XL/28	Elevator Bellcrank Pivot - Inspection	22-Mar-18
Pacific Aerospace 750XL	DCA/750XL/29	Refrigerant Hose Insulation – Inspection	5-Jul-18

Pacific Aerospace 750XL	DCA/750XL/30	Relocation of Ground Terminations – Inspection	5-Jul-18
Pacific Aerospace 750XL	DCA/750XL/31	Firewall Wiring Penetrations – Inspection	5-Jul-18
Pacific Aerospace Cresco 08-600	DCA/CRESCO/20	Elevator Torque Tube - Inspection	7-Jul-16
Pacific Aerospace Cresco 08-600	DCA/CRESCO/21	Engine Oil Pressure Indicator – Replacement	7-Sep-17
Pacific Aerospace FBA-2C series	DCA/FBA/1	Tailplane – Inspection	30-Nov-17
Pacific Aerospace FBA-2C series	DCA/FBA/2	Tailplane Box Attach Fitting – Inspection	30-Nov-17
Pacific Aerospace FBA-2C series	DCA/FBA/3	Forward Wing to Fuselage Attachment – Inspection	30-Nov-17
Pacific Aerospace FU24 Series	DCA/FU24/184	Elevator Torque Tube - Inspection	7-Jul-16
Pilatus PC-12 Series	EASA AD 2014-0170	Cancelled – EASA AD 2016-0083 refers	12-May-16
Pilatus PC-12 Series	EASA AD 2016-0037	Wing to Fuselage Attach Torlon Plates	11-Mar-16
Pilatus PC-12 Series	EASA AD 2016-0081	Engine Mount Frame - Inspection	1-May-16
Pilatus PC-12 Series	EASA AD 2016-0083	Airworthiness Limitations - Amendment	12-May-16
Pilatus PC-12 Series	EASA AD 2017-0024	Primus APEX Build 10 or 10.9 – Amendment	27-Feb-17
Pilatus PC-6 Series	EASA AD 2016-0183	Aileron Mass Balance Counterweight Attachment – Inspection	27-Sep-16
Pilatus PC-6 Series	EASA AD 2016-0202-E	Stabiliser Trim Attachment Structure – Inspection	11-Oct-16
Piper PA-18 Series	FAA AD 81-06-08	Lower Fuselage Attachment Tab – Inspection	25-Jan-18
Piper PA-22 Series	DCA/PA22/118	Cancelled – FAA AD 60-01-07 refers	25-May-17
Piper PA-22 Series	FAA AD 60-01-07	Tail Brace Wires – Inspection	25-May-17
Piper PA-23 & PA-30 Series	FAA AD 2017-15-05	Heater Exhaust Extension – Inspection	28-Aug-17
Piper PA-23 Series	DCA/PA-23/130	Cancelled – FAA AD 2017-15-05 refers	28-Jul-17
Piper PA-23 series	DCA/PA-23/139	Cancelled – Purpose fulfilled	30-Nov-17
Piper PA-23 Series	DCA/PA-23/142B	Stabilator Torque Tube Assembly Bolts - Inspection	28-Jun-18
Piper PA-24 Series	DCA/PA24/113B	Stabilator Torque Tube Assembly Bolts - Inspection	28-Jun-18
Piper PA-28 & PA-32 Series	FAA AD 2017-14-04	Oil Cooler Hoses – Inspection	15-Aug-17
Piper PA-28 Series	DCA/PA-28/127C	Cancelled – FAA AD 2017-14-04 refers	15-Aug-17
Piper PA-28 Series	FAA AD 2015-20-13	Cancelled - FAA AD 2016-07-21 refers	26-Apr-16
Piper PA-28 Series	FAA AD 2016-07-21	Right Wing Rib at Station 140.09 - Inspection	26-Apr-16
Piper PA-28 Series	FAA AD 2018-02-05	Fuel Tank Selector Placards – Inspection	7-Feb-18
Piper PA-28 Series	FAA AD 2018-02-05	Cancelled – FAA AD 2018-07-03 refers	26-Apr-18
Piper PA-28 Series	FAA AD 2018-07-03	Fuel Tank Selector - Inspection	26-Apr-18
Piper PA-30 Series	DCA/PA30/16B	Stabilator Torque Tube Assembly Bolts - Inspection	28-Jun-18
Piper PA-30 Series	DCA/PA-30/8	Cancelled – FAA AD 2017-15-05 refers	28-Jul-17
Piper PA-31 series	DCA/PA31/44B	Cancelled - FAA AD 2016-05-01 refers	15-Apr-16

Piper PA-31 series	FAA AD 2016-05-01	Bulkhead Assembly at Fuselage Station 317.75	15-Apr-16
Piper PA-31 Series	FAA AD 2016-08-18 Correction	Fuel Hose Assemblies - Inspection	6-Jun-16
Piper PA-31 Series	FAA AD 2017-02-06	Wiring below Main Circuit Breaker Panel – Inspection	22-Feb-17
Piper PA-31 Series	FAA AD 2017-10-20	Fuselage Station 332.00 Bulkhead Assembly – Inspection	29-Jun-17
Piper PA-32 Series	DCA/PA-32/50	Cancelled – FAA AD 2017-14-04 refers	15-Aug-17
Reims F406	DCA/REIMS406/6	Cancelled – EASA AD 2016-0101 refers	8-Jun-16
Reims F406	EASA AD 2016-0101	Horizontal Stabiliser Fittings - Inspection	8-Jun-16
Robin DR400 Series	EASA AD 2016-0072 (Correction)	Instrument Panel Electrical Wiring Harness - Inspection	26-Apr-16
Robin DR400 Series	EASA AD 2016-0148	Engine Heated Air Intake Duct – Inspection	5-Aug-16
Robin DR400 Series	EASA AD 2018-0018	NLG Oleo Outer Cylinder Support Plate – Inspection	22-Feb-18
Robin R1180 Series	EASA AD 2018-0017	NLG Oleo Outer Cylinder Support Plate - Inspection	22-Feb-18
Slingsby T67	EASA AD 2015-0065-E	Cancelled - EASA AD 2016-0214 refers	10-Nov-16
Slingsby T67	EASA AD 2016-0214	Brake Master Cylinder Pivot Pins - Inspection	10-Nov-16
Socata TB 9, TB 10 and TB 20	DCA/TB9/29A	Cancelled – EASA AD 2018-0030 refers	22-Feb-18
Socata TB 9, TB 10 and TB 20	EASA AD 2018-0030R1	Wing Front Attachments – Inspection	28-Jun-18
Tecnam P2006T	EASA AD 2018-0029	Rudder Trim Actuator – Life Limitation	14-Feb-18
Thrush S2R-G10 and S2R-T34	FAA AD 2007-26-01	Vertical and Horizontal Stabilisers - Inspection	26-Oct-17
Thrush S2R-G10 and S2R-T34	FAA AD 2009-26-11	Spar Caps - Inspection	26-Oct-17
Univair (Stinson) 108 Series	FAA AD 47-50-11	Ash Tray – Inspection	22-Feb-18
Univair (Stinson) 108 Series	FAA AD 47-50-12	Stabiliser Attachment Fitting – Inspection	22-Feb-18
Univair (Stinson) 108 Series	FAA AD 49-16-02	Wing Fabric – Inspection	22-Feb-18
Univair (Stinson) 108 Series	FAA AD 50-17-02	Rudder Cable – Inspection	22-Feb-18
Univair (Stinson) 108 Series	FAA AD 50-25-01	Fuel Drip Strip – Inspection	22-Feb-18
Univair (Stinson) 108 Series	FAA AD 54-02-02	Wheel Skis – Inspection	22-Feb-18
Univair (Stinson) 108 Series	FAA AD 79-07-02	Batteries – Inspection	22-Feb-18
Yak 52	DCA/YAK/7A	Pneumatic System Reservoirs – Inspection and Replacement	27-Oct-16
<b>Helicopters</b>	<b>Helicopters</b>		
Agusta A109 & A119 Series	EASA AD 2016-0173-E	Tail Rotor Blade Retention Bolts – Inspection	26-Aug-16
Agusta A109 & A119 Series	EASA AD 2017-0176-E	Main Rotor Blades – Inspection	18-Sep-17
Agusta A109 Series	DCA/A109/10	Cancelled – EASA AD 2017-0085-E refers	16-May-17
Agusta A109 Series	EASA AD 2015-0190R1	Cancelled - EASA AD 2016-0213 refers	31-Oct-16
Agusta A109 Series	EASA AD 2016-0213	Main Rotor Blades – Inspection	31-Oct-16

Agusta A109 Series	EASA AD 2016-0261	Fire Extinguisher Bottles – Inspection	4-Jan-17
Agusta A109 Series	EASA AD 2017-0025	Hoist – Inspection	21-Feb-17
Agusta A109 Series	EASA AD 2017-0046-E	Engine and Transmission Oil Cooling System – Inspection	14-Mar-17
Agusta A109 Series	EASA AD 2017-0085-E	Elevator Assembly – Inspection	16-May-17
Agusta A109 Series	EASA AD 2018-0053-E	Swashplate Support - Inspection	22-Mar-18
Agusta A109 Series	EASA AD 2018-0120-E	Baggage Fairings - Modification	31-May-18
Agusta A119 Series	EASA AD 2018-0124	Fuel Control Unit – Inspection	12-Jun-18
Agusta Bell AB206	EASA AD 2016-0117	Cancelled – EASA AD 2018-0028	22-Feb-18
Agusta Bell AB206	EASA AD 2018-0028	Freewheel Lubrication System – Inspection	22-Feb-18
Airbus Helicopters AS 350 Series	DCA/AS350/128C	Forward Two-place Seat - Operating Limitations	22-Mar-18
Airbus Helicopters AS 350 Series	EASA AD 2017-0143	Direct Current (Optional) Second Battery – Replacement	31-Aug-17
Airbus Helicopters AS 355 Series	EASA AD 2017-0159	Fan Assembly - Inspection	8-Sep-17
Airbus Helicopters AS350 & AS355 Series	EASA AD 2011-0164R2	Tail Rotor Control Stop Screws – Inspection	28-Sep-17
Airbus Helicopters AS350 & AS355 Series	EASA AD 2014-0076R1	Rear Structure Junction Frame Reinforcement Angles – Inspection	28-Oct-16
Airbus Helicopters AS350 & AS355 Series	EASA AD 2017-0020-E	Tail Rotor Pitch Rod – Inspection	9-Feb-17
Airbus Helicopters AS350 & AS355 Series	EASA AD 2017-0114	Vertical Fin - Inspection	12-Jul-17
Airbus Helicopters AS350 & AS355 Series	TC AD CF-2017-37	Restriction of Directional Control Pedal Movement	19-Jan-18
Airbus Helicopters AS350 & EC130 Series	EASA AD 2013-0191-E	Cancelled – EASA AD 2017-0052 refers	7-Apr-17
Airbus Helicopters AS350 & EC130 Series	EASA AD 2017-0052	Switches 53Ka, 53Kb and 65K – Inspection	7-Apr-17
Airbus Helicopters AS350 & EC130 Series	EASA AD 2017-0052	Cancelled – EASA AD 2017-0059 refers	13-Apr-17
Airbus Helicopters AS350 & EC130 Series	EASA AD 2017-0059	Switches 53Ka, 53Kb and 65K – Inspection	13-Apr-17
Airbus Helicopters AS350 AS355 & EC130	EASA AD 2017-0089	Main Rotor Mast Upper Bearing Lubrication - Inspection	31-May-17
Airbus Helicopters AS350 Series	DCA/AS350/124	Cancelled – EASA AD 2011-0164R1 refers	28-Feb-17
Airbus Helicopters AS350 Series	DCA/AS350/128B	Forward Two-place Seat - Operating Limitations	30-Jun-16
Airbus Helicopters AS350 Series	DCA/AS350/129	Oceania Aviation Cargo Hook System OAL114 – Inspection	28-Jun-18
Airbus Helicopters AS350 Series	EASA AD 2012-0252	Cancelled – EASA AD 2017-0035 refers	6-Mar-17
Airbus Helicopters AS350 Series	EASA AD 2016-0220	Dual Hydraulic System – Inspection	18-Nov-16
Airbus Helicopters AS350 Series	EASA AD 2016-0260	Main Rotor NR Indicator – Inspection	3-Jan-17
Airbus Helicopters AS350 Series	EASA AD 2017-0035	Twist Grip Assembly – Inspection	6-Mar-17
Airbus Helicopters AS350 Series	EASA AD 2017-0109 (Correction)	Starter Generator and Brushes - Inspection	7-Jul-17
Airbus Helicopters AS350, AS355 & EC130 Series	EASA AD 2017-0032 (Correction)	Main Rotor Hub/Mast Attachment Screws – Inspection	3-Mar-17
Airbus Helicopters AS355 Series	DCA/AS355/93	Cancelled – EASA AD 2011-0164R1 refers	28-Feb-17

Airbus Helicopters AS355 Series	DCA/AS355/97C	Forward Two-place Seat – Operating Limitations	26-Apr-18
Airbus Helicopters AS355 Series	DCA/AS355/98	Oceania Aviation Cargo Hook System OAL114.355 – Inspection	28-Jun-18
Airbus Helicopters AS355 Series	EASA AD 2015-0202	Cancelled - EASA AD 2016-0109 refers	28-Jun-16
Airbus Helicopters AS355 Series	EASA AD 2016-0109R1	Fueltron Flowmeter – Inspection	10-Nov-16
Airbus Helicopters BO105 & MBB-BK117	EASA AD 2016-0142R1	Swashplate Assembly - Inspection	26-Apr-18
Airbus Helicopters Deutschland BO 105 series	DCA/BO105/9	Cancelled - EASA AD 2018-0056 refers	26-Mar-18
Airbus Helicopters Deutschland BO 105 series	EASA AD 2016-0060	Cancelled – EASA AD 2016-0142 refers	2-Aug-16
Airbus Helicopters Deutschland BO 105 series	EASA AD 2016-0118-E	MRB Erosion Protection Shell - Inspection	21-Jun-16
Airbus Helicopters Deutschland BO 105 series	EASA AD 2016-0142	Swashplate Assembly - Inspection	2-Aug-16
Airbus Helicopters Deutschland BO 105 series	EASA AD 2018-0056	Main Rotor Mast - Inspection	26-Mar-18
Airbus Helicopters Deutschland MBB-BK117	DCA/MBB117/24	Cancelled – EASA AD 2010-0058R1 refers	7-Apr-17
Airbus Helicopters Deutschland MBB-BK117	DCA/MBB117/34	Cancelled - EASA AD 2011-0168R1 refers	26-Apr-18
Airbus Helicopters Deutschland MBB-BK117	DCA/MBB117/9	Cancelled – EASA AD 2017-0193 refers	26-Oct-17
Airbus Helicopters Deutschland MBB-BK117	EASA AD 2010-0058R1	Tail Rotor, Cyclic and Collective Control Levers – Inspection	7-Apr-17
Airbus Helicopters Deutschland MBB-BK117	EASA AD 2013-0159	Cancelled – EASA AD 2017-0174 refers	28-Sep-17
Airbus Helicopters Deutschland MBB-BK117	EASA AD 2015-0210R2	Cancelled – EASA AD 2017-0047 refers	27-Mar-17
Airbus Helicopters Deutschland MBB-BK117	EASA AD 2016-0060	Cancelled – EASA AD 2016-0142 refers	2-Aug-16
Airbus Helicopters Deutschland MBB-BK117	EASA AD 2016-0134	Tail Rotor Gearbox Housing - Inspection	22-Jul-16
Airbus Helicopters Deutschland MBB-BK117	EASA AD 2016-0142	Swashplate Assembly - Inspection	2-Aug-16
Airbus Helicopters Deutschland MBB-BK117	EASA AD 2017-0026	Overhead Panel Shock Mounts – Replacement	28-Feb-17
Airbus Helicopters Deutschland MBB-BK117	EASA AD 2017-0037	Rotor Mast Nut and Helical Gear Support - Inspection	8-Mar-17
Airbus Helicopters Deutschland MBB-BK117	EASA AD 2017-0038	Cable Cut Flip Guard - Inspection	8-Mar-17
Airbus Helicopters Deutschland MBB-BK117	EASA AD 2017-0047	Module Plate Assembly - Inspection	27-Mar-17
Airbus Helicopters Deutschland MBB-BK117	EASA AD 2017-0146	Autopilot Operation – AFM Amendment	31-Aug-17
Airbus Helicopters Deutschland MBB-BK117	EASA AD 2017-0174	Time Limits and Maintenance Checks – Airworthiness Limitations Amendment	28-Sep-17
Airbus Helicopters Deutschland MBB-BK117	EASA AD 2017-0177	Outboard Load System – Inspection	28-Sep-17
Airbus Helicopters Deutschland MBB-BK117	EASA AD 2017-0193	Main Rotor Mast – Inspection	26-Oct-17
Airbus Helicopters Deutschland MBB-BK117	EASA AD 2018-0046	Tail Gearbox – Inspection	5-Mar-18
Airbus Helicopters Deutschland MBB-BK117	EASA AD 2018-0061	Blade Thimbles - Inspection	22-Mar-18
Airbus Helicopters Deutschland MBB-BK117 and E	EASA AD 2017-0094	Trim Actuators – Inspection	29-Jun-17
Airbus Helicopters Deutschland MBB-BK117 Serie	EASA AD 2015-0163R1	Doors Jettison System - Removal	27-Apr-16
Airbus Helicopters Deutschland MBB-BK117 Serie	EASA AD 2017-0238	Aircraft Flight Manual (AFM) – Amendment	7-Dec-17



Airbus Helicopters EC120B	DCA/EC120/23	Cancelled – EASA AD 2016-0180 refers	27-Sep-16
Airbus Helicopters EC120B	EASA AD 2016-0180	Emergency Flotation Gear LACU Pushbutton – Inspection and Replacement	27-Sep-16
Airbus Helicopters EC120B	FAA AD 2015-24-51	Cancelled - FAA AD 2017-06-11 refers	8-May-17
Airbus Helicopters EC120B	FAA AD 2017-06-11	Air Conditioner STC SR00491DE – Inspection	8-May-17
Airbus Helicopters EC130	EASA AD 2014-0114R2	Tailboom Fenestron Junction Frame - Inspection and Repair	31-May-18
Airbus Helicopters EC130	EASA AD 2015-0033R1	Cancelled - EASA AD 2016-0240 refers	9-Dec-16
Airbus Helicopters EC130	EASA AD 2016-0240	Tail Boom/Fenestron Junction Frame - Inspection	9-Dec-16
Airbus Helicopters EC130	EASA AD 2016-0240	Cancelled – EASA AD 2017-0066-E	25-Apr-17
Airbus Helicopters EC130	EASA AD 2017-0062	Collective Pitch Control – Inspection	25-Apr-17
Airbus Helicopters EC130	EASA AD 2017-0066-E	Cancelled – EASA AD 2017-0080 refers	19-May-17
Airbus Helicopters EC130	EASA AD 2017-0080	Cancelled – EASA AD 2018-0104 refers	31-May-18
Airbus Helicopters EC130	EASA AD 2018-0104	Tailboom Fenestron Junction Frame - Inspection	31-May-18
Airbus Helicopters EC135 & MBB-BK117	EASA AD 2011-0168R1	Instrument Lighting Display Brightness - Inspection	26-Apr-18
Airbus Helicopters EC135 Series	DCA/EC135/13A	Cancelled – EASA AD 2006-0318R2 refers	25-Apr-17
Airbus Helicopters EC135 Series	DCA/EC135/28	Cancelled – EASA AD 2010-0058R1 refers	7-Apr-17
Airbus Helicopters EC135 Series	DCA/EC135/30A	Cancelled – EASA AD 2017-0002 refers	23-Jan-17
Airbus Helicopters EC135 Series	DCA/EC135/31	Cancelled – EASA AD 2010-0227R1	7-Apr-17
Airbus Helicopters EC135 Series	DCA/EC135/35	Cancelled - EASA AD 2011-0168R1 refers	26-Apr-18
Airbus Helicopters EC135 Series	EASA AD 2006-0318R2	Tail Rotor Linear Control Transducer Bearing and Rod – Inspection	25-Apr-17
Airbus Helicopters EC135 Series	EASA AD 2010-0058R1	Tail Rotor, Cyclic and Collective Control Levers – Inspection	7-Apr-17
Airbus Helicopters EC135 Series	EASA AD 2010-0227R1	Tail Rotor Rod and Ball Pivot – Inspection	7-Apr-17
Airbus Helicopters EC135 Series	EASA AD 2013-0178	Cancelled - EASA AD 2017-0243 refers	21-Dec-17
Airbus Helicopters EC135 Series	EASA AD 2013-0306-CN	AD Cancelled by EASA – Purpose fulfilled	26-Apr-17
Airbus Helicopters EC135 Series	EASA AD 2017-0002	Main Transmission Housing – Modification	23-Jan-17
Airbus Helicopters EC135 Series	EASA AD 2017-0147	Tail Rotor Controls – Modification	31-Aug-17
Airbus Helicopters EC135 Series	EASA AD 2017-0199	Outboard Load System – Inspection	26-Oct-17
Airbus Helicopters EC135 Series	EASA AD 2017-0243	Airworthiness Limitations – Amendment	21-Dec-17
Airbus Helicopters EC135 Series	EASA AD 2018-0063	Cyclic Stick – Modification	26-Apr-18
Airbus MBB-BK-117 & BO105	EASA AD 2015-0166	Cancelled – EASA AD 2016-0060 refers	6-Apr-16
Airbus MBB-BK-117 & BO105	EASA AD 2016-0060	Swashplate Assembly	6-Apr-16
Bell 205 Series	DCA/BELL205/2C	AD Compliance at Initial Airworthiness Certificate Issue	30-Nov-16
Bell 205 Series	FAA AD 2016-22-07	Main Rotor Blades – Inspection	30-Nov-16
Bell 205 Series	FAA AD 2018-02-08	Main Rotor Blades – Inspection	1-Feb-18

Bell 206 Series	DCA/BELL206/107	Cancelled – Transport Canada AD CF-2009-41R1 refers	7-Nov-16
Bell 206 Series	TC AD CF-2009-41R1	Tailboom Attachment Fitting – Inspection	7-Nov-16
Bell 206 Series	TC AD CF-2016-09	Tension Torsion Straps	4-Apr-16
Bell 206 Series	TC AD CF-2016-13	Freewheel Lubrication System – Inspection	16-May-16
Bell 206, 222, 407, 427 & 429 Series	Transport Canada AD CF-2018-16	Seat Belt Comfort Clips – Inspection	28-Jun-18
Bell 212 & 412 Series	FAA AD 2017-15-02	Oil and Fuel Check Valves – Inspection	4-Aug-17
Bell 212 Series	EASA AD 2014-0244	Emergency Flotation System (EFS) – AFM Supplement	31-Aug-17
Bell 212 Series	FAA AD 2000-15-52	Main Rotor Mast - Inspection	31-Mar-16
Bell 212 Series	FAA AD 2001-08-04	Main Rotor Actuator	31-Mar-16
Bell 212 Series	FAA AD 2010-10-16	Cross Tubes	31-Mar-16
Bell 212 Series	FAA AD 2010-26-52	Tail Rotor Blades	31-Mar-16
Bell 212 Series	FAA AD 2011-12-08	Tail Rotor Blades	31-Mar-16
Bell 212 Series	FAA AD 2011-23-02	Main Rotor blades	31-Mar-16
Bell 212 Series	FAA AD 2011-25-01	Liferafts	31-Mar-16
Bell 212 Series	FAA AD 2012-17-08	Main Rotor Head	31-Mar-16
Bell 212 Series	FAA AD 2012-22-06	High Landing Gear Forward Crosstube Assembly	31-Mar-16
Bell 212 Series	FAA AD 2013-03-16	Main Rotor Head	31-Mar-16
Bell 212 Series	FAA AD 2013-06-51	Equipment/Furnishings	31-Mar-16
Bell 212 Series	FAA AD 2013-15-02	Tail Rotor Blades	31-Mar-16
Bell 212 Series	FAA AD 2014-12-04	Main Rotor Head	31-Mar-16
Bell 212 Series	FAA AD 2015-15-04	Main Rotor Blade Grips	31-Mar-16
Bell 212 Series	FAA AD 74-02-01	Tail Rotor Trunion Bearings	31-Mar-16
Bell 212 Series	FAA AD 74-20-05	Elevator	31-Mar-16
Bell 212 Series	FAA AD 75-07-01	High Frequency Vibration	31-Mar-16
Bell 212 Series	FAA AD 76-14-03	Cross Tubes Assemblies	31-Mar-16
Bell 212 Series	FAA AD 78-17-03	Spiral Bevel Gear	31-Mar-16
Bell 212 Series	FAA AD 78-20-07	Shoulder Radius Fitting	31-Mar-16
Bell 212 Series	FAA AD 78-21-02	External Load Link Assembly	31-Mar-16
Bell 212 Series	FAA AD 80-21-05	Landing Gear Cross Tubes	31-Mar-16
Bell 212 Series	FAA AD 81-10-07	Swashplate Support	31-Mar-16
Bell 212 Series	FAA AD 86-17-09	Tail Rotor Hub Assembly	31-Mar-16
Bell 212 Series	FAA AD 90-03-09	Tail Rotor Hub Assembly	31-Mar-16

Bell 212 Series	FAA AD 92-09-05	Torque Adaptor	31-Mar-16
Bell 212 Series	FAA AD 92-13-10	Tail Rotor Driveshaft Hangar Bearing	31-Mar-16
Bell 407 Series	TC AD CF-2016-13	Freewheel Lubrication System – Inspection	16-May-16
Bell 407 Series	TC AD CF-2016-21	Tail Rotor Drive Shaft - Inspection	7-Jul-16
Bell 407 Series	TC AD CF-2017-03	Vertical Fin - Inspection	31-Jan-17
Bell 429 Series	FAA AD 2017-05-51	Air Comm Corp. Air Conditioning System – Inspection	6-Mar-17
Bell 429 Series	TC AD CF-2015-15R1	Pylon Restraint Spring Assy Rod End – Inspection	31-Aug-17
Bell 429 Series	TC AD CF-2015-16R2	Tail Rotor Pitch Link Spherical Bearing – Inspection	17-Apr-17
Bell 429 Series	TC AD CF-2016-01R2	Tail Rotor Pitch Link – Inspection	26-Apr-17
Bell 429 Series	TC AD CF-2016-07	Nose Landing Gear - Service Life Reduction	18-Mar-16
Bell 429 Series	TC AD CF-2016-11R2	Bellcrank Pivot Bearings - Inspection	1-Nov-17
Bell 429 Series	TC AD CF-2016-39	Main Rotor Pitch Link Bearings - Inspection	12-Dec-16
Bell 429 Series	TC AD CF-2017-02	Landing Gear Parts – Life Limitation	30-Jan-17
Bell 429 Series	TC AD CF-2017-16	Time Limits and Maintenance Checks – New Life Limitations	31-May-17
Bell 429 Series	TC AD CF-2017-23	Goodrich Hoists – Inspection	21-Jul-17
Bell 505 Series	TC AD CF-2017-36	Engine Chip Detector – Inspection	29-Dec-17
Bell UH-1 Series	DCA/UH1/1C	AD Compliance at Initial Airworthiness Certificate Issue	28-Apr-16
Bell UH-1 Series	FAA AD 2016-23-09	Main Rotor Blades - Inspection	27-Dec-16
Bell UH-1 Series	FAA AD 2018-02-07	HTC Main Rotor Blades P/N 204P2100-101 - Inspection	1-Feb-18
Guimbal Cabri G2	EASA AD 2014-0196	Cancelled – EASA AD 2016-0033 refers	9-Mar-16
Guimbal Cabri G2	EASA AD 2016-0032	Airworthiness Limitations	9-Mar-16
Guimbal Cabri G2	EASA AD 2016-0033	Cancelled – EASA AD 2017-0039 refers	10-Mar-17
Guimbal Cabri G2	EASA AD 2017-0039	Engine Cooling Fan – Inspection	10-Mar-17
Helicopters - General	DCA/HELI/10	Non-Conforming Dinitrol Products	27-Jul-17
Helicopters - General	DCA/HELI/11	Differential or Specialist GPS Installations – Confirm Approved Installation Data	21-Dec-17
Helicopters - General	DCA/HELI/6	Engine Control Rod Eye Ends - Modification	27-Jul-17
Helicopters - General	DCA/HELI/7	Cable End Assemblies - Proof Load	27-Jul-17
Helicopters - General	DCA/HELI/8	Emergency Exits – Inspection	27-Jul-17
Helicopters - General	DCA/HELI/9	Passenger and Crew Compartment Interiors – Inspection and Replacement	27-Jul-17
Kawasaki BK117 Series	DCA/BK117/18A	Cancelled – JCAB AD TCD-4114A-1-2008 refers	30-Jun-16
Kawasaki BK117 Series	DCA/BK117/1B	Airworthiness Directive Compliance	26-May-16
Kawasaki BK117 Series	DCA/BK117/6	Cancelled - JCAB AD TCD-4655A-2017	30-Nov-17
Kawasaki BK117 series	DCA/BK117/9A	Cancelled – TCD-5126B-2016 refers	16-Mar-16

Kawasaki BK117 Series	JCAB AD TCD-9082-2018	Main Rotor Transmission Helical Gear Support – Inspection	31-Jan-18
Kawasaki BK117 Series	JCAB AD TCD-9106-2018	Tail Rotor Transmission Bellcrank Attach Arm – Inspection	27-Apr-18
Kawasaki BK117 series	JCAB AD TCD-9114-2018	Main Rotor Blade Thimble – Inspection	31-May-18
Kawasaki BK117 Series	JCAB TCD-4114-2-2004	Cancelled – JCAB AD TCD-4114A-1-2008 refers	30-Jun-16
Kawasaki BK117 Series	JCAB TCD-4114A-1-2008	MRB Balance Weight - Inspection	30-Jun-16
Kawasaki BK117 Series	JCAB TCD-4655A-2017	Main Rotor Mast – Inspection	30-Nov-17
Kawasaki BK117 series	JCAB TCD-5126B-2016	Airworthiness Limitations	16-Mar-16
Kawasaki BK117 Series	JCAB TCD-6217-2003	Tail Rotor and Intermediate Gearbox - Inspection	26-May-16
Kawasaki BK117 Series	JCAB TCD-6273-2003	Vertical Fin Skin Panel – Inspection	26-May-16
Kawasaki BK117 Series	JCAB TCD-7000-1-2008	One Engine Inoperative (OEI) – Operating Limitations	26-May-16
Kawasaki BK117 Series	JCAB TCD-7000-2006	One Engine Inoperative (OEI) – Operating Limitations	26-May-16
Kawasaki BK117 Series	JCAB TCD-7111-2007	Fire Extinguishing System – Inspection	26-May-16
Kawasaki BK117 Series	JCAB TCD-8201C-2016	Goodrich Rescue Hoists - Inspection	17-Jun-16
Kawasaki BK-117 Series	JCAB TCD-8811-2016	Tail Rotor Transmission Housing – Inspection	22-Aug-16
Leonardo AW169 Helicopters	EASA AD 2017-0137	Collective Fixed Friction Force	22-Feb-18
Leonardo AW169 Helicopters	EASA AD 2017-0155	Emergency Exit Windows	22-Feb-18
Leonardo AW169 Helicopters	EASA AD 2017-0156	Automatic Flight Control System	22-Feb-18
Leonardo AW169 Helicopters	EASA AD 2017-0164	Landing Gear Retraction Actuators	22-Feb-18
Leonardo AW169 Helicopters	EASA AD 2017-0255	MLG Weight on Wheels Support Bracket	22-Feb-18
MD Helicopters MD369	FAA AD 2016-04-15	Main Rotor Blade Attach Pin	31-Mar-16
MD Helicopters MD369	FAA AD 2016-05-09	Auxiliary Fuel Pump	15-Apr-16
Robinson R22 Series	DCA/R22/27C	Cancelled - DCA/R22/48 refers	26-May-16
Robinson R22 Series	DCA/R22/48	Revised Operating Limitations – AFM Amendment	26-May-16
Robinson R22 Series	DCA/R22/49	Bladder Fuel Tanks – Retrofit	22-Mar-18
Robinson R22 Series	DCA/R22/50	Helipod III Spray System STC 7/21E/9 – Removal from Service	22-Mar-18
Robinson R22 Series	DCA/R22/51	Helipod NZ Limited STCs – Report of Installation	22-Mar-18
Robinson R44 Series	DCA/R44/34	Revised Operating Limitations – AFM Amendment	26-May-16
Robinson R44 Series	DCA/R44/35	Instrument Markings	24-Nov-16
Robinson R44 Series	DCA/R44/36	Helipod NZ Limited STCs – Report of Installation	22-Mar-18
Robinson R44 Series	FAA AD 2016-26-04	Main Rotor Blades – Inspection	8-Feb-17
Robinson R66	DCA/R66/1	Instrument Markings	24-Nov-16
Robinson R66	FAA AD 2016-26-04	Main Rotor Blades – Inspection	8-Feb-17
Sikorsky 269 Series	DCA/HU269/113	Helipod NZ Limited STCs – Report of Installation	22-Mar-18

Sikorsky 269 Series	DCA/HU269/96	Cancelled – FAA AD 2017-14-06 refers	25-Aug-17
Sikorsky 269 Series	FAA AD 2017-14-06	Lower Coupling Driveshaft – Inspection	25-Aug-17
Sikorsky S-76 series	FAA AD 2001-03-51	Main Rotor Shaft Assembly – Inspection	30-Nov-17
Sikorsky S-76 series	FAA AD 2012-22-13	Engine Controls – Inspection	30-Nov-17
Sikorsky S-76 series	FAA AD 2017-19-01	Main Rotor Servo Pushrod Assembly – Inspection	2-Jan-18
Sikorsky S-76 series	FAA AD 2018-10-07	Engine Collective Position Transducer (CPT) – Inspection	25-Jun-18
Sikorsky S-76 series	FAA AD 99-01-09	Fuel Supply Line - Inspection	30-Nov-17

### Amateur Built Microlights

### Amateur Built Microlights

Microlights	UK CAA MPD 2016-008-E	Wing Luff Line Attachment Webbing – Inspection	3-Oct-16
Microlights	UK CAA MPD 2016-009	Hang Bolt Installation – Inspection	25-Nov-16
Microlights	UK MPD 2016-011-E	Clevis Pin/Split Ring Installations – Inspection	30-Mar-17
Microlights	UK MPD 2017-003-E	Hang Bolt plus Lanyard – Inspection	21-Feb-17
Microlights - DUC FLAIR-2 Propellers	EASA AD 2017-0092-E	DUC Propellers H-FLR2 (FLAIR-2) – Remove from Service	23-May-17
Microlights - P & M Aviation Ltd	UK MPD 2017-004-E	Rigging Cables with Roll Swaged End Terminals – Inspection	15-May-17

### Ex-military and Vintage Aircraft Factory Built – Not type certified

### Ex-military and Vintage Aircraft Factory Built – Not type certified

Ex-military and Vintage Aircraft Factory Built – Not type certified	UK CAA MPD 2016-010	Main Rotor Hub Torsion Bars – Inspection	7-Oct-16
Ex-military and Vintage Aircraft Factory Built – Not type certified	UK MPD 2016-001R1	Engine Fuel System Aging Effects – Inspection	24-Feb-17
Ex-military and Vintage Aircraft Factory Built – Not type certified	UK MPD 2017-002-E	Main Rotor Gearbox Controls – Inspection	20-Feb-17

### Gliders

### Gliders

Alexander Schleicher Gliders	EASA AD 2016-0192	Rudder Control System – AFM Amendment	12-Oct-16
Alexander Schleicher Gliders	EASA AD 2017-0136	Exhaust Silencer – Replacement	31-Aug-17
DG-Flugzeugbau Gliders	EASA AD 2016-0259	Fuel Hoses – Inspection	4-Jan-17
DG-Flugzeugbau Gliders	EASA AD 2018-0032	Air Brake Control Handle – Inspection	1-Mar-18
DG-Flugzeugbau Gliders	EASA AD 2018-0127	Fuel Hoses – Inspection	28-Jun-18
Glasflugel & Schempp-Hirth Gliders	EASA AD 2017-0167-E	Front Electric Sustainer/Battery Pack - Modification	28-Sep-17
Glasflugel Gliders	EASA AD 2012-0073	Elevator Control Rod in Vertical Fin - Inspection	28-Sep-17
Grob Gliders	EASA AD 2016-0228	Tail Wheel Mounting Bracket – Inspection	28-Nov-16
L-13 Blanik Gliders	EASA AD 2011-0135R3	Wing Main Spar – Inspection	31-Aug-17
Schempp-Hirth Gliders	EASA AD 2016-0027R1	Airbrake Panels	2-Mar-16

Slingsby T61 Series Gliders	UK CAA AD G-2018-0001	Revised Life Limitations	22-Feb-18
Stemme S10 Series Gliders	EASA AD 2017-0072-E	Front Gearbox – Inspection	28-Apr-17
<b>Balloons</b>	<b>Balloons</b>		
Balloons	EASA AD 2016-0151	Burner and Fuel Hoses - Inspection	9-Aug-16
Balloons	EASA AD 2018-0107 (Correction)	Lindstrand T30 Propane Cylinders – Removal from Service	31-May-18
Balloons	FAA AD 2016-17-04R1	Burner and Fuel Hoses – Inspection	6-Sep-16
<b>Engines</b>	<b>Engines</b>		
Continental Motors	DCA/CON/129A	Throttle Body Support Structure - Inspection	31-Aug-17
Continental Motors	FAA AD 2011-25-51	Starter Adaptor Shaft Gear - Inspection	25-Aug-16
Continental Motors	FAA AD 2016-16-12	ECi Cylinder Assemblies – Inspection	15-Sep-16
Continental Motors	FAA AD 2016-21-04	Oil Cooler Cross Fitting – Inspection	18-Nov-16
Continental Motors	FAA AD 69-09-01	Eisemann Magnetos - Inspection	25-Aug-16
Continental Motors	FAA AD 69-24-03	Carburettor - Inspection	25-Aug-16
Continental Motors	FAA AD 70-14-07	Fuel Injection Pump - Inspection	25-Aug-16
Continental Motors	FAA AD 72-24-03	Oil Filter Adaptor - Inspection	25-Aug-16
Continental Motors	FAA AD 77-13-22	Crankcase Cracks - Inspection	25-Aug-16
Continental Motors	FAA AD 79-05-09	Oil Pump Assembly or Pressure Relief Valve and/or Plunger - Inspection	25-Aug-16
Continental Motors	FAA AD 80-06-05	Magnetos - Inspection	25-Aug-16
Continental Motors	FAA AD 86-13-04R3	Cylinder Assemblies	25-Aug-16
Continental Motors	FAA AD 87-14-02	Starter Adaptor Shaft Gear - Inspection	25-Aug-16
Continental Motors	FAA AD 88-17-03	Starter Adaptor Shaft Gear - Inspection	25-Aug-16
Continental Motors	FAA AD 93-19-04	Carburettor - Inspection	25-Aug-16
Engines - General	FAA AD 2018-02-04	Mufflers - Inspection	21-Feb-18
GE Aviation Czech (formerly Walter Engines) M601 Series	EASA AD 2017-0100	Power Turbine Disc – Replacement	29-Jun-17
GE Aviation Czech (formerly Walter Engines) M601 series engines	EASA AD 2017-0151	Exhaust System – Modification	1-Sep-17
Honeywell TPE331 Series	FAA AD 2015-12-04	Cancelled – FAA AD 2016-21-07 refers	28-Nov-16
Honeywell TPE331 Series	FAA AD 2016-18-17	2 <sup>nd</sup> Stage Compressor Impeller – Inspection	4-Nov-16
Honeywell TPE331 Series	FAA AD 2016-21-07	Woodward Fuel Control Unit Assemblies – Inspection	28-Nov-16
Honeywell TPE331 Series	FAA AD 2018-02-14	Combustion Chamber Case Assembly – Inspection	28-Feb-18
Honeywell TPE331 Series	FAA AD 2018-13-05	Hydraulic Torque Sensor Gear Assembly – Inspection	26-Jul-18
Lycoming AEIO-320, IO-320 and LIO-320 series engines	FAA AD 2017-16-11	Connecting Rod Small End Bushings – Inspection	15-Aug-17

Lycoming AEIO-360, HIO-360, IO-360 and LIO-360 series engines	FAA AD 2017-16-11	Connecting Rod Small End Bushings – Inspection	15-Aug-17
Lycoming AEIO-390 and IO-390 series engines	FAA AD 2009-02-03	Fuel Injection Servos – Inspection	26-Oct-17
Lycoming AEIO-390 and IO-390 series engines	FAA AD 2012-03-06	Fuel Servo Diaphragms – Inspection	26-Oct-17
Lycoming AEIO-390 and IO-390 series engines	FAA AD 2012-19-01	Crankshafts – Inspection	26-Oct-17
Lycoming AEIO-540 and IO-540 series engines	FAA AD 2017-16-11	Connecting Rod Small End Bushings – Inspection	15-Aug-17
Lycoming AEIO-580 & IO-580 Series	FAA AD 2004-10-14	Crankshaft Gear – Inspection	25-May-17
Lycoming AEIO-580 & IO-580 Series	FAA AD 2009-02-03	Fuel Injection Servos – Inspection	25-May-17
Lycoming AEIO-580 & IO-580 Series	FAA AD 2012-03-06	Fuel Servo Diaphragm – Inspection	25-May-17
Lycoming AEIO-580 & IO-580 Series	FAA AD 2012-19-01	Crankshafts – Inspection	25-May-17
Lycoming AEIO-580 & IO-580 Series	FAA AD 2015-02-07	Propeller Governor Shaft Set Screw – Inspection	25-May-17
Lycoming AEIO-580-B1A and IO-580-B1A series engines	FAA AD 2017-16-11	Connecting Rod Small End Bushings – Inspection	15-Aug-17
Lycoming HO-360, LO-360 and O-360 series engines	FAA AD 2017-16-11	Connecting Rod Small End Bushings – Inspection	15-Aug-17
Lycoming IO-720 engines	FAA AD 2017-16-11	Connecting Rod Small End Bushings – Inspection	26-Oct-17
Lycoming LTIO-540 and TIO-540 Series Engines	FAA AD 2017-11-10	Engine Exhaust System – Inspection	28-Jun-17
Lycoming LTIO-540 and TIO-540 series engines	FAA AD 2017-16-11	Connecting Rod Small End Bushings – Inspection	15-Aug-17
Lycoming O-235 series engines	FAA AD 2017-16-11	Connecting Rod Small End Bushings – Inspection	15-Aug-17
Lycoming O-320 series engines	FAA AD 2017-16-11	Connecting Rod Small End Bushings – Inspection	15-Aug-17
Lycoming O-540 series engines	FAA AD 2017-16-11	Connecting Rod Small End Bushings – Inspection	15-Aug-17
Pratt & Whitney PT6 Series	DCA/PT6/25A	SOAR 98 Engine Escalation Program	28-Jun-18
Pratt & Whitney PT6 Series	Transport Canada AD CF-2015-01R1	Engine Torque Indication – Inspection	2-Dec-16
Rolls-Royce 250 Series	DCA/AL250/58	Number 5 Bearing P/N M250-10106 - Replacement	13-Apr-16
Rolls-Royce Avon series	UK MPD 2018-002	Engine Calendar Life Limits	26-Apr-18
Rolls-Royce Avon series	UK MPD 2018-004	Stages 1 to 4 Compressor Blades and Discs - Inspection	31-May-18
Rolls-Royce Avon series	UK MPD 2018-005-E	Front Compressor Casing - Inspection	28-Jun-18
Rolls-Royce Corporation 250 series engines	FAA AD 2015-02-22	Cancelled – FAA AD 2017-18-14 refers	13-Oct-17
Rolls-Royce Corporation 250 series engines	FAA AD 2017-18-14	Third and Fourth Stage Turbine Wheels - Inspection	13-Oct-17
Rolls-Royce Viper MK 522	EASA AD 2015-0127R1	Cancelled – EASA AD 2017-0148 refers	31-Aug-17
Rolls-Royce Viper MK 522	EASA AD 2017-0148	Engine Critical Parts – Reductions of Cycle Life Limits	31-Aug-17
Rolls-Royce Viper MK 522	G-002-07-90	Engine Center Section	31-Mar-16
Rolls-Royce Viper MK 522	G-0049 PRE 80	Engine Fuel Pump	31-Mar-16

Rolls-Royce Viper MK 522	G-008-11-97	Augmentor and By-pass Valve Assembly to BFCU	31-Mar-16
Rolls-Royce Viper MK522	EASA AD 2015-0127R1	Engine Critical Parts	31-Mar-16
Rolls-Royce Viper MK522	G-002-07-90	Engine Center Section	31-Mar-16
Rolls-Royce Viper MK522	G-003-02-96	Fuel Pump Types MGBB.183 and MGBB.184	31-Mar-16
Rolls-Royce Viper MK522	G-0046 PRE 80	Engine Fuel Servo to EPC Tube Unit	31-Mar-16
Rolls-Royce Viper MK522	G-0047 PRE 80	Compressor Blow-off Valve	31-Mar-16
Rolls-Royce Viper MK522	G-0048 PRE 80	Blow-off Valve	31-Mar-16
Rolls-Royce Viper MK522	G-0049 PRE 80	Engine Fuel Pump	31-Mar-16
Rolls-Royce Viper MK522	G-008-11-97	Augmentor and By-pass Valve Assembly to BFCU	31-Mar-16
Rolls-Royce Viper MK522	G-010-10-80	Exhaust Cone Assembly	31-Mar-16
Rolls-Royce Viper MK522	G-011-11-97	BFCU	31-Mar-16
Rolls-Royce Viper MK522	G-030-04-90	Engine Lubrication	31-Mar-16
Rolls-Royce Viper MK522	G-050-09-89	Engine Compressor	31-Mar-16
Rotax Engines	EASA AD 2016-0144 (Correction)	Carburettor Float – Inspection	26-Jul-16
Rotax Engines	EASA AD 2017-0101-E	Ignition Housing Sealing Plug – Inspection	13-Jun-17
Rotax Engines	EASA AD 2017-0208	Valve Push Rod Assembly – Inspection	27-Oct-17
Rotax Engines	UK CAA MPD 2017-001	Cylinder Head – Inspection	11-Feb-17
Rotax Engines	UK CAA MPD 2017-005-E	Ignition Housing Sealing Plug – Inspection	9-Aug-17
Rotax Engines	UK CAA MPD 2018-001	Valve Push Rod Assembly – Inspection	22-Feb-18
Safran Helicopter Engines Arriel 1 Series	DCA/TUR/47	Cancelled – EASA AD Cancellation Notice 2007-0045-CN refers	22-Feb-18
Safran Helicopter Engines Arriel 1 Series	DCA/TUR/6A	Cancelled - DGAC AD 92-078R2 refers	25-Jan-18
Safran Helicopter Engines Arriel 1 Series	DGAC AD 92-078R2	Reduction Gearbox Module (MO5) – Inspection	25-Jan-18
Safran Helicopter Engines Arriel 1 Series	EASA AD 2015-0064R1	Cancelled – EASA AD 2017-0061 refers	29-Jun-17
Safran Helicopter Engines Arriel 1 Series	EASA AD 2017-0019R1	Cancelled - EASA AD 2017-0064-E refers	14-Apr-17
Safran Helicopter Engines Arriel 1 Series	EASA AD 2017-0061	Cancelled - EASA AD 2018-0003 refers	25-Jan-18
Safran Helicopter Engines Arriel 1 Series	EASA AD 2017-0064R2	Engine Fuel Drain Valve Assembly - Inspection	26-Apr-18
Safran Helicopter Engines Arriel 1 Series	EASA AD 2018-0003	Airworthiness Limitations – Amendment	25-Jan-18
Safran Helicopter Engines Arriel 2 Series	DCA/TUR/51	Cancelled – EASA AD Cancellation Notice 2007-00117-CN refers	22-Feb-18
Safran Helicopter Engines Arriel 2 Series	EASA AD 2007-0063	Hydro-Mechanical Metering Unit Fuel Filter Drain Screw – Inspection	27-Oct-16
Safran Helicopter Engines Arriel 2 Series	EASA AD 2009-0010R1	Digital Engine Control Unit (DECU) Software – Modification	27-Oct-16
Safran Helicopter Engines Arriel 2 Series	EASA AD 2010-0215R1	Cancelled – EASA AD 2017-0102 refers	29-Jun-17
Safran Helicopter Engines Arriel 2 Series	EASA AD 2011-0249	Digital Engine Control Unit (DECU) – Inspection	27-Oct-16



Safran Helicopter Engines Arriel 2 Series	EASA AD 2013-0170R1	Hydro-mechanical Metering Unit – Inspection	25-Apr-17
Safran Helicopter Engines Arriel 2 Series	EASA AD 2015-0177	Cancelled – EASA AD 2017-0121 refers	31-Jul-17
Safran Helicopter Engines Arriel 2 Series	EASA AD 2016-0055R1	Accessory Gearbox Module M01 – Inspection	11-Oct-16
Safran Helicopter Engines Arriel 2 Series	EASA AD 2016-0235	Engine Front Support - Inspection	8-Dec-16
Safran Helicopter Engines Arriel 2 Series	EASA AD 2017-0102	HP/LP Fuel Pump Metering Unit – Inspection	29-Jun-17
Safran Helicopter Engines Arriel 2 Series	EASA AD 2017-0121	Airworthiness Limitations - Amendment	31-Jul-17
Safran Helicopter Engines Arriel 2 Series	EASA AD F-2004-192	Torque Confirmation Box – Inspection	27-Oct-16
Safran Helicopter Engines Arrius 2 Series	EASA AD 2008-0018	Electronic Engine Control (EEC) Unit – Inspection	27-Oct-16
Safran Helicopter Engines Arrius 2 Series	EASA AD 2016-0003R1	Main Injector Half-manifolds - Replacement	6-Dec-16
Safran Helicopter Engines Arrius 2 Series	EASA AD 2018-0044	Gas Generator (Module 02) / Power Turbine Wheel – Replacement	28-Feb-18
Safran Helicopter Engines Arrius 2F Series	DCA/TUR/48	Cancelled – EASA AD 2007-0057R1 refers	26-Apr-18
Safran Helicopter Engines Arrius 2F Series	EASA AD 2007-0057R1	Gas Generator Front Bearing - Modification	26-Apr-18
Safran Helicopter Engines Arrius 2F Series	EASA AD 2016-0138R1	Cancelled – EASA AD 2017-0070 refers	9-May-17
Safran Helicopter Engines Arrius 2F Series	EASA AD 2017-0070	Pipe Injector Preferred Assembly – Inspection	9-May-17
Safran Helicopter Engines Arrius 2F Series	EASA AD 2018-0012-E	Electrical Magnetic Plug – Inspection	18-Jan-18
Solo 2625 Series Engines	EASA AD 2016-0254	Fuel Injection System Control Unit - Modification	29-Dec-16
Technify Motors TAE 125 Series	DCA/THIE/22	Cancelled – EASA AD 2010-0136R1 refers	16-Aug-16
Technify Motors TAE 125 Series	EASA AD 2010-0136R1	Engine Timing Chain – Inspection	16-Aug-16
Technify Motors TAE125 Series	EASA AD 2017-0034R1	Gearbox – Inspection	25-Jan-18
Turbomeca Engines	DCA/TUR/79	Cancelled – EASA AD 2011-0218R1 refers	4-May-16
Turbomeca Engines	DCA/TUR/86A	Cancelled – EASA AD 2016-0138 Refers	28-Jul-16
Turbomeca Engines	EASA AD 2011-0218R1	Power Turbine Blades – Life Limitation	4-May-16
Turbomeca Engines	EASA AD 2015-0162	Cancelled - EASA AD 2016-0055 refers	31-Mar-16
Turbomeca Engines	EASA AD 2016-0041	Fuel Control Unit Assembly	17-Mar-16
Turbomeca Engines	EASA AD 2016-0055	Accessory Gearbox Module M01	31-Mar-16
Turbomeca Engines	EASA AD 2016-0090	Centrifugal Impeller – Life Limitation	24-May-16
Turbomeca Engines	EASA AD 2016-0098	Hydro-Mechanical Metering Unit - Modification	6-Jun-16
Turbomeca Engines	EASA AD 2016-0138	Privilege Injectors – Modification	28-Jul-16

## Propellers

## Propellers

Hamilton Standard Propellers	FAA AD 50-12-01	Propeller Blades Model 11C1 (Navy 4350, 4350F & 4350F1) – Inspection	29-Sep-16
DUC Hélices H-FLR2 (FLAIR-2) Series	EASA AD 2017-0092R1	Propeller Hub and Blades - Modification	28-Jun-18
Hoffmann Propellers	DCA/HOF/1	Cancelled - EASA AD 2017-0220 refers	30-Nov-17
Hoffmann Propellers	EASA AD 2017-0220	Propeller Blades – Inspection	30-Nov-17

Components & Equip**	Components & Equip**	Components & Equip**	Components & Equip**
Aircraft Seats and Harnesses	DCA/SEAT/13	Helicopter Seating Systems – Inspection	28-Jul-16
Aircraft Seats and Harnesses	EASA AD 2017-0225	Seat Restraint Systems – Inspection	1-Dec-17
Avionics	DCA/RAD/54E	Artex 406 ELT(AF) – Inspection and Modification	30-Jun-16
Avionics	FAA AD 2017-22-14	Rockwell Collins Traffic Surveillance Units – Inspection	20-Dec-17
Avionics Equipment	FAA AD 2017-16-01	Ameri-King ELTs – Inspection	24-Oct-17
Electrical - Aluminium Wire - Inspection and Replacement	DCA/ELECT/43A	Cancelled - Purpose fulfilled	29-Sep-16
Electrical - Bendix Dual Magnetos - Inspection	DCA/ELECT/24B	Cancelled – Purpose fulfilled	29-Sep-16
Electrical - Bendix Magneto - Inspection	DCA/ELECT/27A	Cancelled – Purpose fulfilled	29-Sep-16
Electrical - Bendix Magneto Capacitors - Inspection	DCA/ELECT/25	Cancelled – Purpose fulfilled	29-Sep-16
Electrical - Bendix Magneto, Rotating Magnet - Inspection	DCA/ELECT/28A	Cancelled – Purpose fulfilled	29-Sep-16
Electrical - Bendix Magnetos - Inspection	DCA/ELECT/32	Cancelled - Purpose fulfilled	29-Sep-16
Electrical - Bendix Magnetos - Inspection	DCA/ELECT/34	Cancelled - Purpose fulfilled	29-Sep-16
Electrical - Bendix Magnetos - Inspection	DCA/ELECT/38	Cancelled - Purpose fulfilled	29-Sep-16
Electrical - Bendix Magnetos - Replacement of Brass Housing Capacitors	DCA/ELECT/26	Cancelled – Purpose fulfilled	29-Sep-16
Electrical - Bendix Magnetos Impulse Coupling	DCA/ELECT/39	Cancelled - Purpose fulfilled	29-Sep-16
Electrical - Bendix Starting Vibrators - Modification	DCA/ELECT/36	Cancelled – Purpose fulfilled	29-Sep-16
Electrical - Magneto Coils and Rotating Magnets - Replacement	DCA/ELECT/47A	Cancelled – Purpose fulfilled	29-Sep-16
Electrical - Magneto Coils and Rotating Magnets - Replacement	DCA/ELECT/48	Cancelled - Purpose fulfilled	29-Sep-16
Electrical - Pulselite Units - Removal	DCA/ELECT/45	Cancelled - Purpose fulfilled	29-Sep-16
Electrical - Slick Magnetos, Coil Installation – Inspection	DCA/ELECT/37	Cancelled - Purpose fulfilled	29-Sep-16
Electrical - TCM Magneto Capacitor - Replacement	DCA/ELECT/46	Cancelled - Purpose fulfilled	29-Sep-16
Electrical Equipment - Aircraft Engines	DCA/ELECT/51E	TCM and Bendix Magnetos – 500hr Inspection	30-Nov-17
Emergency Equipment	DCA/EMY/41	Life Preserver – Inspection	27-Oct-16
Emergency Equipment	EASA AD 2016-0042-E	Emergency Parachute Harnesses	4-Mar-16
Emergency Equipment	EASA AD 2016-0044	Engine and APU Automatic Fire Extinguishers	22-Mar-16
Emergency Equipment	EASA AD 2016-0062	Emergency Parachute Harnesses	23-Mar-16
Emergency Equipment	FAA AD 2016-11-20	Cancelled – FAA AD 2017-18-12 refers	16-Oct-17

Emergency Equipment	FAA AD 2017-18-12	B/E Aerospace Protective Breathing Equipment – Inspection	16-Oct-17
Emergency Equipment	FAA AD 2017-19-05	Siemens Smoke Detectors – Inspection	31-Oct-17
Engine & APU Automatic Fire Extinguishers	UK AD G-2015-0001	Cancelled - EASA AD 2016-0044 refers	22-Mar-16
Instruments	FAA AD 2017-04-06	United Instruments 5934 series Altimeters – Inspection	7-Apr-17
Role Equipment - Helicopters	EASA AD 2015-0226R3 (with revised applicability)	Goodrich Hoists – Inspection	27-Jul-17
Seats and Harnesses	EASA AD 2016-0210	Seat Energy Absorber Assembly – Inspection	7-Nov-16
Seats and Harnesses	UK CAA AD 002-12-2001R2	Sutton Safety Harnesses – Inspection and Life Limitation	31-Aug-17

**Notes:**

\* The AD Schedule often covers a complete series of types.

\*\* This is not the AD Schedule title but more specific to the components affected.

\*\*\* AD Numbering - If the AD number is less than 10, a zero has been added before the number.

This is for sorting only and the AD should still be referred to as in the AD Schedule.